WHITEFISH CREEK BRIDGE (BRIDGE 3355)

SHPO INV. # ML-KAN-005

Location:

Bridge 3355 is located on T.H. 169 about 300 feet north of CSAH 25 in Mille Lacs County's Kathio Township. The bridge allows the Whitefish Creek to flow under TH 169 into Mille Lacs Lake at Wigwam Bay.

Introduction: The Whitefish Creek Bridge (#3355) was built in two sections: the original bridge was a 16'-0" section built in 1921. The bridge was added onto and enlarged by the CCC in 1939 to its current width of 76'-0". Its headwalls and railings are built of gray random ashlar, rusticated Isle granite. H.O. Skooglun of the National Park Service designed the structure. Metal guardrails currently extend from each end of the headwalls. The highway was repaved and the guardrails extended during the summer of 2000.

Architect's Survey Date: October 6, 1999

Plans/Sketches:

- 1. 01/39 Reinforcing Design Plan
- 2. 01/39 Design Bridge Plan-Existing Conditions as of 10/99
- 3. Site plan sketch (MJBA 10/99)
- 4. 03/29/68 Letter MnDOT "Central Files" expressing concerns about the load capacity of the bridge
- 5. Dept. of Highways, Bridge Maintenance...(Note: 7/8/78 repairs)
- 6. MNHD Roadside Development Plans T.H. 169-18, Sheets 1 and 7 of 8
- 7. FHA Photos of Wood Timber/Steel and Stone Masonry Guardrails samples

MNDOT HISTORIC ROADSIDE DEVELOPMENT STRUCTURES INVENTORY

ML-KAN-005 CS 4814 Whitefish Creek Bridge (Bridge 3355)

Historic Name Other Name	Whitefish Creek Bridge (Bridge 3355)		CS # SHPO Inv #	4814 ML-KAN-005
Location	TH 169 300' N of CSAH 25		Hwy District Reference	TH 169 3A 227.7
City/Township County	Kathio Mille La	Township	Acres	
Twp Rng Sec		7W Sec 7	Rest Area Class	NA
USGS Quad	Vinelan		Tiour Area Glade	147.1
UTM	Z15 E	438860 N5118080	SP #	169-18-23-4 1804-08
Designer	Skooglun, H O, Natl Park Serv			1804-08
	Nichols	, A R, Consult Land Arch	OUDO D	
Builder	Civilian Conservation Corps (CCC)		SHPO Review #	
Historic Use	Historic Use Bridge/ Culvert/ Dam		MHS Photo #	013535.20-24
Present Use	Bridge/ Culvert/ Dam			
Yr of Landscape Design		1939	MnDOT Historic Photo Album	Nic 1.21
Overall Site Integrity		Intact/Slightly Altered		
Review Required		Yes		
National Register Status		Eligible, see Statement of Significa	ance	
Historic Context		Roadside Development on Minnes Reinforced Concrete Highway Brid	- ·	20-1960
List of Chandina Co				

List of Standing Structures

Feat#	Feature Type	Year Built	Fieldwork Date
01	Bridge/Culvert	1939	08-03-97
			Prep by
			Gemini Research
			Dec. 98 G1. 94
			Prep for
			Site Development Unit
			Cultural Resources Unit
NOTE:	Landscape features are not	listed in this table	Environmental Studies Unit

Stabilization/Preservation/Restoration

1. Spatial Organization and Land Patterns

- a. Functional Relationships:
 - Assessment: The Whitefish Creek Bridge (Bridge 3355) is a granite-faced concrete slab bridge that carries Whitefish Creek under T.H. 169 and into Mille Lacs Lake at Wigwam Bay. The bridge was designed in the National Park Service Rustic Style to blend with its natural setting and to visually enhance T.H. 169 (then part of the "Minnesota Scenic Highway") while at the same time serving a utilitarian engineering function. Except for plantings, the site is generally intact in size and spatial organization.

Recommendations:

Stabilization: None.

Preservation/Restoration: Purchase the parking area directly southwest of the bridge to provide for a small screened parking area, picnicking and walking. Plant new turf and trees near the parking lot that complement the Rustic Style design and place two or three wooden picnic tables, a privy and several trash receptacles throughout this area. Add interpretive signage to inform the visitors about the bridge's history and the CCC's work along T.H. 169, etc. Work Period: 1 - 3 years.

b. Visual Relationships:

• Assessment: The Bridge was designed to be viewed by vehicles driving over it, but today is easily missed by cars driving at 50-60 mph. The recently extended steel guardrails overwhelm the masonry structure, obscuring its presence to the motorist unless one is specifically looking for it.

The bridge's design enhances the view of the highway in this scenic area and provides visual interest to the nearby resorts, cabins, and beaches. Again, the metal guardrails overwhelm the design. Today the bridge is best seen from either the beach or from a privately owned parking area located southwest of the structure.

The view from the bridge includes Mille Lacs Lake to the east, forest and wetlands to the west, forests to the north, and resorts and cabins to the south. There is a private parking area immediately southwest of the bridge. A condominium building and marina can be seen across the bay to the northeast.

The setting has changed little since the 1930s except that cabins to the west have been razed and buildings to the south have been remodeled. There are also more cars on the highway. Future commercial and resort development in the vicinity is likely and T.H. 169 is scheduled to be widened to a four-lane highway and/or realigned. The wetlands to the west and the lake to the east may serve to buffer the bridge somewhat from surrounding development.

Recommendations:

Stabilization: None.

Preservation: Clear brush from the western side of the bridge to improve its visibility. Work Period: ASAP.

Restoration: Clear brush from the western side of the bridge to bring it into view. Acquire additional acreage west and southwest of the bridge, including the privately owned parking area, to protect the site's visual context. If a new T.H. 169 roadway is built west of the current alignment, plant appropriate natural buffers to screen the new, modern highway from the historic bridge similar to the way that the T.H. 169 4-lane is screened from CSAH 35 just north of the Grand Casino at Vineland. Work Period: 1-3 years.

2. Topography

- <u>Assessment:</u> The site is flat except at the banks of the creek and ditches along T.H. 169.
- Recommendations: None.

3. Vegetation

Assessment Original landscaping plans from the 1930s (S.P. 4814-10) intended that T.H. 169 be lined with evergreens and shade trees, and that the bridge be set off with pines. This landscaping was part of a 2.8-mile Roadside Development project. Sheet 7 of the plan specifies that 32 "Western Yellow Pine" (Pinus Ponderosa) be placed in four groups of eight at the four corners of the bridge. Twenty American Elm were to be planted on the right-of-way just south of the bridge at the intersection of the highway and CSAH 25 (groups of 10 were to be placed on the northwestern and southwestern corners of the intersection). Twenty Green Ash were to be planted on both sides of T.H. 169 at Sta. 343-346.5, about 600' south of the bridge. Finally, between Sta. 328.67 and 350 (extending 1,000' north and 1,100' south of the bridge), 13,310 unspecified evergreen transplants were to be installed on both sides of T.H. 169. (See plans for S.P. 4814-10 for details on the thousands of evergreens, American Elms, Green Ash, and Lombardy Poplars that were planted as part of the 2.8-mile project.)

Today the bridge is surrounded by grassy highway ditches, the sandy beach of Lake Mille Lacs, and dense woods to the west and north, including a large stand of evergreens. The pines, elms, most of the ash, and some of the evergreen transplants specified on the plans are missing in the immediate environs of the bridge but may be still standing in the forest to the north and west. Trees and brush growing along Whitefish Creek are currently obscuring the western facade of the bridge. Weeds are encroaching on the bridge's walkways and curbs.

Recommendations:

Stabilization and Preservation: cut back weeds and brush from the bridge to a distance of 6'. Reseed with appropriate groundcover to reduce erosion. Establish and follow a regular schedule of mowing and trimming. Work Period: Cut back brush ASAP; other work—annually and routine maintenance

Restoration: Restore the original planting plan for the bridge and nearby right-of-way. If plants specified in the original plans are not available, use substitute plants of similar size, shape, color, and texture. Establish and follow a regular schedule of mowing and trimming. Work Period: 1 - 3 years and provide annual and routine maintenance.

4. Circulation

a. Access:

• <u>Assessment:</u> Traffic on T.H. 169 is often heavy and now travels at 50-60 mph, considerably faster than when the bridge first opened. Because of the volume and speed of the traffic, slowing to view the bridge is dangerous.

In 2000, the highway over the bridge was resurfaced with an overlay that raised the elevation of the pavement about 3". There is a gravel shoulder between the edge of this pavement and the bridge's flagstone walkway and curb. The portion of the gravel shoulder closest to the curb was not disturbed during the 2000 overlay. About 3" of the curb's original 8" curb face is currently exposed above the gravel on the western side of the highway. Little, if any, of the curb face is exposed on the eastern side of the highway. During the 2000 improvements, the metal guardrails extending from the ends of the bridge were lengthened. Their added length has visually overwhelmed the stonework.

T.H. 169 is scheduled to be widened to a four-lane highway in the near future. In one of the proposed alternatives, T.H. 169 would be realigned several hundred feet to the west and this portion of "old" T.H. 169 would become a county highway serving the lakeshore. If the road eventually becomes a county highway, traffic over the bridge may be lighter.

Recommendations:

Stabilization: Cut weeds back from stone curbing and keep the bridge weed-free. If the bridge is eventually transferred to county ownership because T.H. 169 is realigned, take steps to insure the bridge's future preservation and proper maintenance after the transfer. Work Period: Weeds—ASAP; maintenance—annually.

Preservation: Cut weeds back from stone curbing and keep the bridge weed-free. If the bridge is eventually transferred to county ownership because T.H. 169 is realigned, take steps to insure the bridge's future preservation and proper maintenance after the transfer. Work Period: Weeds—ASAP; maintenance—annually.

Restoration: Lower the elevation of the highway paving and gravel shoulder to increase the visibility of the stonework and restore the original curb depth. (Costs of highway modifications are not included in this document.)

If the bridge is eventually transferred to the county because T.H. 169 is realigned, take steps to insure the bridge's future preservation and proper maintenance after the transfer.

It is recommended that the highway speed limit over the bridge be reduced to 45 mph. Work Period: 1 - 5 years.

b. Pedestrian walks

• Assessment: The Bridge has 4'-wide granite flagstone walkways located just inside the stone railings. Newer roadway grades have covered parts of the edges and most of the surfaces have settled and/or heaved and are overgrown with vegetation and covered with roadway sand and gravel. Currently there is no pedestrian footpath extending north and south of the bridge and none is recommended. Today, walking from the highway right-of-way, across the bridge, and across the highway are not safe due to the speed and amount of traffic. The bridge is most safely approached from the parking area to the southwest and along the wide sandy beach.

Current plans for the reconstruction of T.H. 169 include discussion of a possible bike trail along the western shore of Mille Lacs that would presumably cross the bridge.

Recommendations:

Stabilization: None.

Preservation and Restoration: Despite the fact that pedestrian travel over the bridge is not recommended, the flagstone walkways should be carefully preserved because they are an integral part of the bridge structure (see Sidewalk under Structures below). Acquire the parking area southwest of the bridge (see Parking Areas below). Participate in plans for possible future development of a bike trail over the bridge. Work Period: 3 - 5 years. Land acquisition costs are not included.

c. Parking Areas

• <u>Assessment:</u> The Bridge was not designed with a parking area. The only possible parking is on a privately owned parking area, which is not currently in use, at the southwestern corner of the bridge. This parking area provides an excellent view of the bridge and pedestrian access to its western face.

• Recommendations:

Stabilization/Preservation and Restoration: Acquire the parking area southwest of the bridge to provide safe public access to the bridge, provide a location for an interpretive marker, and buffer the bridge from inevitable future development. It is recommended that this acquisition be explored as soon as possible during this quiet time in the development of the immediate vicinity. If the parking area is acquired, redesign it for about 5-8 cars and landscape the remaining area with appropriate plants (inspired by S.P. 4814-10), an interpretive marker, and perhaps a portable picnic table based on historic MHD designs. Work Period: 1 - 3 years.

5. Water Features: Not applicable

6. Structures, Furnishings and Objects

a. Bridge/culvert

• Assessment: It is in generally good condition and is structurally sound. Maintenance is required. The "Bridge Maintenance, Repairs and Renewals" records show that the masonry was cleaned and regrouted and sidewalks repaired in 1978. Tops of walls are covered with about one inch of concrete topping. Condition of the mortar topping is poor. At the south end of the east wall about 2'-0" of the topping is missing. Many stone joints are in poor condition or are missing. Granite stones are missing in a few spots. Green paint (graffiti) is located on the southwest side of the west wall. Vegetation is overgrown along the walls. Exposed foundations of round fieldstone are visible at the banks of each wall indicating that the grade has settled since it was built.

Recommendations:

Stabilization, Preservation and/or Restoration: Completely remove the concrete topping from the walls and clean all exposed stone. Remove all mortar from all joints and prepare for repointing. Repoint all joints including the topside joints of the walls. Cutback the existing vegetation along the base of the walls to remove and repair and repoint all fieldstone foundation joints. The faces of the stone at the bridgeheads shall be cleaned and all graffiti removed from the stone in the locations named above. Replace missing stones with matching granite and/or fieldstone. Stabilize the grade to prevent erosion following masonry restoration. Work Period: 3-5 years.

b. Curb, stone

• Assessment: Original drawings show the curb about 8" above the roadway surface. In 2000, the highway over the bridge was resurfaced with an overlay that raised the elevation of the pavement about 3". There is a gravel shoulder between the edge of the asphalt pavement and the bridge's flagstone walkway and curb. The portion of the gravel shoulder closest to the curb was not disturbed during the 2000 overlay. About 3" of the curb's original 8" curb face is currently exposed above the gravel on the western side of the highway. Little, if any, of the curb face is exposed on the eastern side of the highway.

Recommendations:

Stabilization: Remove all weeds. Work Period: ASAP and annually.

Preservation and Restoration: Remove all weeds. Regrade the driving surface to expose the curb and restore the elevation of the flagstone walking surfaces along the bridge walls as originally designed. Work Period: 3 - 5 years.

c. Guardrail, metal

• <u>Assessment:</u> During the 2000 improvements, the metal guardrails extending from the ends of the bridge were lengthened. Their added length has visually overwhelmed the stonework.

Recommendations:

Stabilization: Replace existing with timber-faced metal guardrail that is visually appropriate for the stone masonry bridge walls. See enclosed photo example. Work Period: 1 - 3 years.

Preservation: Replace the metal guardrails with a stone masonry guardrail, similar to the picture included. Work Period: 1 - 5 years.

Restoration: Replace the metal guardrails with a stone masonry guardrail, similar to the picture included. Work Period: 1 - 5 years.

d. Sidewalk

• <u>Assessment:</u> Existing flagstone is in fair to good condition. Parts of the walks are covered from a buildup of sand, gravel, and vegetation. Much of the walking surface is uneven due to freeze/thaw actions and neglected maintenance.

Recommendations:

Stabilization: None.

Preservation/Restoration: Cut down asphalt driving surface to expose original 8" high concrete curb. Install new driving surface to match original grades. Repair de-

teriorated curb as described above. Remove all flagstone and catalog original location to re-install in those locations. Regrade all substrate material on which the flagstone rests. Add sand as needed and compact. Re-install existing flagstone and provide new matching stone using Isle granite for those pieces that are missing. Provide regular maintenance. Work Period: 3 - 5 years.

- 7. Accessibility Considerations: Does not apply.
- 8. Health and Safety Considerations: All construction and masonry restoration materials and methods shall be environmentally approved for the preservation of the water quality standards in the lake and creek. Extra safety precautions are needed while construction work is completed due to the high volume and speed of the traffic. No pedestrian movement over TH 169 is recommended.
- 9. Environmental Considerations: Not applicable
- 10. Other Considerations/Recommendations: Signage is recommended to be done as soon as possible to raise the public's awareness of this site's historic importance and educational value. Provide a sign on each side of the highway indicating the historic bridge's location so that motorists may choose to stop on the west side to get a closer look at the construction methods used by the CCC during the 1930's. Locate an interpretive plaque in the acquired parking area that tells a brief story of the CCC and the historic roadside construction. If the parking area cannot be acquired, then the interpretive signage should be eliminated for highway safety.
- 11. Conclusion: The restoration of this bridge is critical due to the near future highway changes proposed. MnDOT's acquisition of the adjacent parking area to the west is imperative and should occur as soon as possible. The parking area is currently an "eyesore" and will provide a small, safe picnicking and interpretative area for travelers.

Because the guardrails serve a very useful purpose and fulfill safety requirements, they must be maintained. However, because of their length and current metal design, they significantly and negatively impact the stone bridge and its visual historic value. Therefore the replacement of these metal rails with historically sensitive designs that are already approved by the Federal Highway Administration must be undertaken when the bridge repairs occur.

Provide interpretive signage that describes the history of the site, its designers and builders. The panel design should be simple and unobtrusive. If necessary, create a sensitively designed, hard-surfaced access to the panel such as "grass-crete."

	Stabilization	Preservation	Restoration
Spatial Organization and Land Patterns	Otabilization	r reservation	restoration
Off-site impacts			
Functional relationships			
Visual relationships			
Cultural landscape limits (land acquisition)			
Topography			
Character-defining feature			
Non-contributing corrective work			
Vegetation	\$2,860	\$2,860	\$45,530
Circulation		. ,	
Access road and internal roadways (guardrail costs below)			
Parking areas	\$33,754	\$33,754	\$33,754
Pedestrian walks		\$12,953	\$15,356
Paths and trails			
Water Features			
Structures, Furnishings and Objects			
Bath house			
Bench(es), other			
Bench(es), stone			
Bridge/culvert	\$72,125	\$72,125	\$72,125
Cave	Ψ' Ε, 1ΕΟ	Ψ1 Ε, 1ΕΩ	Ψ12,12 <u>0</u>
Council ring			
Curb, stone	\$562	\$6,477	\$6,477
Curb, concrete	\$30Z	φυ,477	φυ,477
Dan			
Dock			
Drinking fountain(s)			
Entrance Wall			
Fireplace(s), other			
Fireplace(s), stone			
Flagpole(s), other			
Flagpole(s), stone			
Flagstone pad			
Footbridge			
Foundation of building			
Gravestone			
Guardrail, stone (Replace w/historic)	(Timber/Steel) \$18,304	(Stone Masonry) \$154,880	(Stone Mas.) \$154,880
Info board			
Info booth			
Marker			
Other feature			
Overlook wall			
Picnic shelter(s)			
Picnic table(s), other		\$2,640	\$2,640
Picnic table(s), stone			
Privies		\$880	\$880
Refuse container(s), stone			
Restroom building			
Retaining wall			
Rock garden			
Sea wall			
Sidewalk			
Signpost, other			
Signpost, stone			
Spring water outlet			
Statue Status as hailding			
Storage building			
Trail steps			
Wall			
Well/pump	1		
Accessibility Considerations			
Health and Safety Considerations			
Environmental Considerations			
Other Considerations (signage)	\$6,336	\$6,336	\$6,336
ESTIMATED COSTS	\$133,941.00	\$292,904.00	\$337,978.00
	- Company of the Comp	1	


Guardrail/wall Options that are historically appropriate.



Wood Timber/steel Reinforced Guardrail



Stone Masonry Guardwall






- ARCHITECTURE
- INTERIOR DESIGN
- HISTORIC PRESERVATION

MICHAEL J. BURNS ARCHITECTS, LTD.

824 CENTER AVENUE, MOORHEAD, MN 56560 ■ 2878 LILAC LANE NE, FARGO, ND 58102 ■ (218) 233-6620 ■ (701) 298-0140 ■ FAX: (218) 233-6621

Project Mandot RPA Project No. 9919

Subject WHITERSH BRIDGE 3355 Date 10-6-99



CENTRAL FILES

E. E. Johnson Bridge Maintenance Supervisor March 29, 1968

G. H. Kolstad Chief, Centralized Operations

Bridge #3355 on T.H. 169, 4.7 miles north of Vineland

Herewith one set of prints for the slab span Bridge #3355.

It has been suggested that this structure should have a thorough reinspection as there are some aspects which may have been over loosed in the routine annual inspection.

This structure originally built as a 16' slab span with 19' between curbs in 1920 was subsequently widened in 1939. The grade has been raised so that the curbs are no longer visible on the old structure or perhaps they were cut off in the widening process and there is a question as to just what the present dead load consists of.

It should be noted as to whether or not any deficiencies are showing up which could be a result of overloading on both the new and the old portion. It would be of interest to determine the exact depth of fill and what it consists of as to whether or not it is bituminous material, gravel, and so forth.

Please give this your early attention and advise.

Attachment: Prints

cc:

J. L. Spencer

D. J. Aune

A. L. W. Anderson

R. P. Braun

GHK:1t

STATE OF MINNESOTA 5.P. 169-18-23-4=4814 FORM 510-6M4-27 DEPARTMENT OF HIGHWAYS. BRIDGE MAINTENANCE, REPAIRS AND RENEWALS DATE BRIDGE NO 3355 MAINT NO 815 LOCATION SEC. 7 TWP. 43 RGE 27 TH.NO COUNTY Mille LOCS STREAM WHITE FISH CREEK OCATED 4.7 MILES N FROM Vineland YEAR BUILT 1920 BUILT BY Milaca Br. Co. COS, OF CONSTRUCTION \$ 2750 00 DESCRIPTION 16' 5/0b 16 WIDTH OF ROADWAY TYPE FLOOR CONC. REPAIRS COMPLETED 2-24 EST.COST DATE COST REPAIRS RECOMMENDED DATE 1937 Reflector Buttons+ Repairs Brita & T 125.61 Widowd Nath Park Service Labership 1930 1225,00 Ropers. 19.86 1939 Muc Pr. Manit of Twof M . 1 - - 1. 910 1941 146.50 REPAIRING 1958 22.03 Plus 7314 Man Lours CCC, 1959 11.77 Inspection 2659.12 Mail erial by State 1937 5.98 615.65 /960 Misc. Repairs Enqueening FS1112/1151in 1961 By Arez 3-B 1.8-78 PEPSIR S. DELLALKS 8.80 1,189 69 weathering mortar shows snorth weathering

CONVENTIONAL SIGNS & ABBREVIATIONS

CONV	ENTIONAL SIGNS & ABBREVIA	lions
STATE LINE	TIMBER	TRUNK HIGHWAY RALINE
TOWKSHIP OR RANGE LINE	BRUSH	RAUROAD RYWLINE
		PRESENT ROAD PALINE
	ORCHARD.	EXCAVATION
	ORCHARD	EARTH
		LOOSE ROCK LR
	ROCK LEDGE	SOLID ROCK
CORPORATE OR CITY LIMITS	SAND.	EMBANKMENTF.
TOURSE HIGHWAY CENTER LINE		OVERHAUL
DETAINING WALL	EDGE OF CUT	NAME DITCHING N.D.
	TO OF EMBARCHENT	SPECIAL EXCAVATION
ELECTRIC RAILROAD	CATCH BASIN.	SPECIAL PLOWING
KAURUM ROBER OF WAR LINE	MARHOLE	GUARD RAILGR
CREEK	FIRE HYDRANT	CORRUGATED METAL CALVERT
PAPIDS OR WATERFALL	ARC LAMP	SECTIONAL CONCRETE CULVERT PICHAL SECTIONAL CONCRETE CULVERT (Newsy Type) Packal
DRY RUN	OTHER LAMPS (Style Kord)	TON MILES THE
DRAINAGE DITCH	RAILROAD CROSSING SIGN	TELEPHONE POLE TELP
DRAMAGE DITCH	RAILROAD CROSSING BELL	POWER POLE P.P.
HIGH TENSION LINE	ELECTRIC WARNING SIGN	PLACE
	CROSSING GATE	INPLACEINP
CHUFFITS DI AM	CATTLE GUARD	REPLACE
		RIGHT
MATTER MATTER STATE OF THE STAT	OVERHEAD (Hopmany Over)	шп
DROP INLET	THE	INTERSECTION ANGLE
	UNDERPASS (Bullion, Under)	TANGENT
WIRE FENCE		LENGTH OF CURVEL
BOARD OR RESIDENCY SHOW FENCE	ABUTHENT, WALL & PIER)	PORT OF CURVE P.C.
	, , ,	POINT OF TANGENT
WW. 10000000	GIRDER BRIDGE	POINT OF INTERSECTION
	TRU55	VERTICAL CURVE
		BENCH MARK
DRAM TILE	TRESTLE	ELEYATION
GRAYEL PIT	BUILDING (One Story Frame)	ACRESA
SAND PIT	F-FRAME C-CONCRETE 75"	V
CLRY PIT	B-BRICK ST-STUCIA	r
POCK QUARRY	IRON PIPE	1
SPRINGS.	STONE MONUMENT	- A
37KH03	WOOD STAKE OR HUB	. ^
MARSH	MEANDER CORNER	1 /A
The state of the s	4	
	(1) C	5-1-3
913	A OF	£ 35 36 ₽
-(*/3) -	- 1300	× 211 ×
(:33)		V
4	PA PA	WILL STATE OF THE
سي ا	TE: SECTION NUMBERS SHOULD BE MADE TO READ FROM THE	MINOE
NO.	F. SCHOOL MALECUS SECOND DE LANS TO HOST HOLT HE	

GENERAL NOTES

Location of proposed trees & shrubs shall be adjusted on the ground to conform to existing conditions such as clearance of overhead wires, sight clearance on curves, outcropping rock, and other fixed local factors.

All tree noies to be 3' in diameter and 3' in cepth. Dackfilled with 12° of clay and

24° of loam, unless otherwise designated.

24° of loam, uncess otherwise designated.

Shrubs & vines are to be installed in beds lôt in depth and backfilled with 6° of clay & 12° of loam unless designated on plans as hole panting.

Shrubs & ones designed as hole planting are to be installed in holes 18" in Cameter 5.18" in depth and backfilled with 6" of clay & 12" of loam

Planting along the open road shall be informal and natural in arrangement, avoiding straight lines in the installation of individual plants.

LETTING DATE		APPROVED		19	-	
GPOSS LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
EXCEPTIONS-LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
NET LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
LETTING DATE		APPROVED		19	DALTBECT EAST-WEEK	
GROSS LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
EXCEPTIONS-LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
NET LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
LETTING DATE		APPROVED		19	SASTRACT EAGREES	
GROSS LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
EXCEPTIONS-LENGTH	Feet	Miles	Feet	Miles	Feet	Miles
NET LENGTH	Feet	Miles	Feet	Miles	Feet	Miles

STATE OF MINNESOTA


DEPARTMENT OF HIGHWAYS ROADSIDE DEVELOPMENT PLANS TRUNK HIGHWAY NO. 169-18

BETWEEN N. LINE MILLE LACS CO. AND 1/2 MILE SOUTHERLY OF WHITE FISH CREEK
From A POINT 737.5' EAST OF N W COR. OF
TO SEC. 16. TAS M - RZTW.
TO SEC. 16. TAS M - RZTW.

Scale 1 Inch = 10560 Feet

, SECTION MINNESOTA NO. GROSS LENGTH 14793.2 FEET 2.802 MILES MILES BRIDGE 3-LENGTH FEET EXCEPTIONS-LENGTH FEET MILES NET LENGTH 14793.2 FEET 2.802 MILES LAYOUT

> IN COOPERATION WITH WORK PROJECTS ADMINISTRATION



Title Sheet and Layout Map Estimate Sheet

ROADSIDE DEVELOPMENT PLANS CONVENTIONAL SIGNS

EXISTING PLANT GROWTH FOLIAGE INDICATION AT RELATIVE SCALE COMMON (ENGLISH) NAMES


WOOD, FOREST OR GROVE	
SHADE TREE. D = INCH DIAMETER AT BREAST RENGHT - 4½ FT S = SPREAD IN FEET OR 1½ X INCH DIAMETER	
EVERGREEN TREE (SCREEN TYPE)	<i>X</i>
FLOWERING TREE (SMALL TREE OR SHRUB TYPE)	
SHRUB MASS (SINGLE OR GROUPED)	
HEDGEROW	
CLIPPED HEDGE	VIAMALIA SULLANDIS

PROPOSED (TO BE PLANTED) CLASSIFICATION BASED ON RELATIVE SIZE AT MATURITY SCIENTIFIC (LATIN) NAMES

SHADE TREE	9 (6)
FIGURES WITHIN CIRCLES ROICATES VARIETY OF	F TREE ACCORDING TO KEY MIDEX
FLOWERING TREE	F TREE ACCORDING TO KEY INDEX
EVERGREEN TREE	TIRE ACCORDED TO KEY MORE
SPECIMEN TREE	OLARGE OR SMALLO
SMALL TREES IN GROUPS	
LARGE SHRUBS IN GROUPS	
MEDIUM SIZE SHRUBS	95 LONICERA MORROWI 5'
GROUND COVER FIRST PIGURE INDICATES QUANTITY LAST FIGURE INDICATES SPACING IN FEET	Ci2 O
TO BE TRANSPLANTED - FROM - TO	
TO BE REMOVED	
VIEW LINES	
UNDESTRABLE OUTLOOKS	Ісин
Right of Way Approval	S TI
4	1 (10

Roadside Development Approval	THE HEEK OF KOND HOM DEVELOPMENT
Plan-ed by	ENGINCER OF PLANS
Recommended for Approval	EMBLES OF SURVEY AND DESIGN
Recommended for Approval	DISTRICT CHRONICAL
Recommended for Approval	Constituction (second)
Approved19	Cond/ EmbricES

DESIGN SOUAD FRED YOUT





1. East Side looking North



2. Looking North along TH 169



3. North End of the East Wall looking NE



4. West Wall looking North



5. North Wall looking South (Curb is not visible)



6. West Wall looking South (overgrown turf)



7. Close-up of Flagstone Walk



8. Close-up of Granite Header over Culvert



9. Close-up of Mortar Joint Condition.



11. Mortar Topping at Walls (broken and spalling)



13. Patched End Caps (spalled mortar topping above sloped stone patch and loose mortar behind)



10. Missing Stone and Poor Mortar



12. Mortar Joint Conditions



 Wall End showing Poor Mortar Conditions and Overgrown Vegetation



15. Granite/Fieldstone Foundation



16. Granite/Fieldstone Foundation (Note: fill settling)



 Culvert Opening (Note: Condition of granite header and surrounding mortar joints)



18. Graffiti on West Wall



 Culvert Condition Showing Granite, Concrete and Water Level Variations

Whitefish Creek Bridge (Bridge 3355)

SITE BOUNDARIES

■ RECOMMENDED BOUNDARY OF NATIONAL REGISTER-ELIGIBLE PROPERTY

The recommended boundary of the National Register-eligible property is shown by the dashed line on the accompanying sheets entitled "Whitefish Creek Bridge (Bridge 3355) Site Boundaries." The base maps for these sheets are a Minnesota Department of Transportation (Mn/DOT) Right-of-way Map and a Mn/DOT aerial photo.

The eastern boundary of the National Register-eligible property follows the Mn/DOT right-of-way line, which is also the shoreline of Mille Lacs Lake. The western boundary follows the Mn/DOT right-of-way line and the bank of Whitefish Creek, as shown. The northern and southern boundaries are drawn at points 100' north and 100' south of the bridge's midpoint.

Boundary Justification

The recommended boundary of the National Register-eligible property encompasses the bridge and its original plantings. The plantings originally extended north and south approximately 100' from the midpoint of the bridge and east and west to approximately the right-of-way lines (see plans for S.P. 4814-10).

■ RECOMMENDED BOUNDARY OF MN/DOT HISTORIC SITE CONSERVATION ZONE

The recommended boundary of the Mn/DOT Historic Site Conservation Zone is also shown on the accompanying sheets. The Conservation Zone encompasses both the National Register-eligible property, marked by the dashed line, and adjacent areas marked by the solid line.

Boundary Justification

The Mn/DOT Historic Site Conservation Zone is recommended to provide a special management zone that includes both the National Register-eligible site and a larger area that encompasses part of the historic property's early physical and visual "context" or setting.

Preserving the property's physical and visual setting will help protect its historic integrity and enhance the public's understanding of, and appreciation for, the historic site design. The Conservation Zone will help buffer the site from elements that may detract from its historic character.

It is recommended that the Conservation Zone boundaries include the National Register-eligible property and additional land described as follows:

North and south of the National Register-eligible property, it is recommended that the Conservation Zone include all Mn/DOT right-of-way extending along the trunk highway 400' north and 400' south of the eligible property. West, northwest, and southwest of the National Register-eligible property, it is recommended that the Conservation Zone extend to a line 200' west of the National Register-eligible property, as shown.

MN/DOT HISTORIC ROADSIDE DEVELOPMENT STRUCTURES INVENTORY - SITE BOUNDARIES

ML-KAN-005 CS 4814

Whitefish Creek Bridge (Bridge 3355)

It is recommended that Mn/DOT retain all current right-of-way within the Conservation Zone. It is further recommended that Mn/DOT preserve the Conservation Zone by taking such actions as special right-of-way planting and maintenance, acquiring additional property or scenic easements, and/or creating partnership agreements with individuals or groups interested in preserving the historic property and its setting. The Mn/DOT Cultural Resources Unit should be consulted regarding these activities.

In particular, it is recommended that Mn/DOT replant and maintain its right-of-way within the Conservation Zone following historic photos and original planting plans (see sheet 7 of 8 of S.P. 4814-10).

It is further recommended that Mn/DOT purchase the 200'-deep Conservation Zone area west, northwest, and southwest of the National Register-eligible site. This parcel is one of few locations near the bridge where a visitor can park, safely view the bridge, and walk to the bank of Whitefish Creek. After acquisition, it is recommended that Mn/DOT provide safe public access to the bridge, an interpretive marker, and appropriate plantings to buffer the bridge from future nearby development that may detract from its historic character. It is recommended that the parcel be redesigned with a small parking area, an interpretive marker, a picnic table based on historic MHD designs, and plantings consistent with S.P. 4814-10. (It is also recommended that the Whitefish Creek Bridge be jointly interpreted with other CCC-built sites in the area. For more information, see the site boundary recommendations for Garrison Concourse, Garrison Pedestrian Underpass, and the T.H. 169 Culvert at St. Alban's Bay.)

■ MORE INFORMATION

For detailed information on the Whitefish Creek Bridge's structures, landscape, and significance, refer to:

Mn/DOT Historic Roadside Development Structures Inventory form for Whitefish Creek Bridge (Bridge 3355) (Gemini Research, Dec. 1998).

"Mn/DOT Historic Roadside Development Structures Preservation and Restoration Report" for Whitefish Creek Bridge (Bridge 3355) (Michael J. Burns Architects and Gemini Research 2001).

Prepared by Gemini Research May 1, 2004.



Sheet 1 of 2
Prep by Gemini 2003

CS 4814

